



Tyco 801AP MX Programming & Service Tool

Part No.: 516.800.918

Tyco 801AP MX Programming & Service Tool 516.800.918

The Tyco 801AP MX Service Tool is a powerful and flexible tool, designed to assist in the installation, commissioning, diagnostics and service of Tyco MX Fire Detection Systems.

Tyco 801AP allows all of the MX addressable devices to be interrogated, tested and programmed. It has a 32-character backlit LCD alphanumeric display, arranged in 2 rows of 16 characters and 4 softkeys.

Features

- ✓ Read/write the detector/ancillary address
- ✓ Display date of manufacture and commissioning
- ✓ Programming of the LED
- ✓ Display serial number
- ✓ Display temperature/ CO levels / smoke obscuration
- ✓ Testing the detector remote LED and control outputs
- ✓ Perform the detector self verification test function
- ✓ Displaying detector dirtiness level
- ✓ Controlling ancillary outputs
- ✓ Reading ancillary statuses
- ✓ Power management options
- ✓ Product Code: 801AP (516.800.918)

