

Humidity and Temperature Sensor for Continuous High Humidity

Part No.: EE211

Technical Specification

Measuring range –Humidity	0...100 % RH
Measuring range –Temperature	-40...60 °C (-40...140 °F),
Sensing element	heated for high humidity operation, E+E proprietary coating
Output analogue	0-5 V / 0-10 V / 4-20 mA (2-wire) / 0-20 mA (3-wire)
Output digital	Modbus RTU

